



This short gooseneck is the only lead component that was on most* of the service lines that contain or previously contained lead

The green water mains on the map were updated and no longer have the lead gooseneck.

*We are currently aware of one home in the Village with a lead service line.

All service lines originally installed copper

Remaining water lines to be updated

